

# GOOD LUCK LINKS


## Necklace Tutorial



Need

- 18g raw copper wire
- Labradorite chips
- Beading wire
- Ring mandrel
- Flush cutters
- 2 Flat nose pliers
- 3mm/5mm Wubber
- Jewelry file
- Jewelry hammer and bench block
- Copper crimp beads
- Crimper

1



Use flush cutters to snip 7, 2.75" pieces copper wire.

2



Using 3mm side of wubber, create loop on each end of each wire piece.

3



Wrap and shape around ring size 4 on mandrel.

4



Hammer horseshoe shape with loops flat, then flip hammer and use other side to texturize.

5



Holding piece with fingers or flat nose pliers, grip each loop w/ 2nd plier & turn perpendicular.

6



Create 7 links and connect together. You may have to pinch the loop side of links to make links connect easily and move freely together.

7



Use 5mm side of wubber to create jump ring and S-shape link. Once formed, hammer and texturize.

8



Attach formed jump ring to loops on last link, then connect S-link to that. Crimp desired length of beading wire to free end of S-link.

9



String labradorite and crimp other end to round side of first link in chain.

Pro Tip

You might be wondering, where's the clasp!? Creating a fancy chain link like the S-link we made can create an invisible clasp. Just barely open the end connected to the jump ring + voila!